



Case Study

Brighton Bandstand

Since 1969 **Cemplas Waterproofing and Concrete Repairs Limited** have been providing cost effective Waterproofing and remedial repair solutions to many prestigious projects, and are proud to have been appointed in the refurbishment of the Bandstand, and to have played a part in prolonging the life of this historic structure

Cemplas who are widely regarded as one of the leading restoration firms in the South East providing a unique and unrivalled range of design and implementation services, undertook both the internal and external specialist works which were backed by their own 10 year Guarantee.

The run down dilapidated basement of the building was very wet and damp, and remedial works included grit blasting the soffits, walls, and floors together with the badly corroded supporting filler joists.



Once all the preparation works had been completed, Cemplas then went about undertaking reinstatement of all the remedial concrete repairs.

On completion of the concrete repairs, the basement floor and walls were fully waterproofed with an epoxy tanking system, and a DPC was injected into both the external perimeter & internal walls.

Extensive external works included Cemplas undertaking concrete repairs to the existing cill around the perimeter of the building, together with specialist render repairs, and the removal and repair of over 150 brackets and outlets.

Cemplas were also tasked with fully waterproofing the Podium deck of the bandstand.

For further details contact:

Paul Stacey at Cemplas on **0208 654 3149**
or **email: info@cemplas.co.uk**

